National Powersports-Pembroke
319 Commerce Way
Pembroke, NH 03275
603-410-4120

Repair Order Summary

339807

****The Repair Order documents the parts and labor that we invested in preparing this vehicle for resale, and is not an additional charge.****

Qty	Part Description	Price	Amount
0	GASKET DERBY COVER 5 HOLE	$10.95	0.00
1	HF171C OIL FILTER CHROME	$12.34	12.34
2	ORING DRAIN PLUG	$0.95	1.90
1	HEAVY DUTY PRIMARY CHAINCASE OIL BULK	$4.93	4.93
4	SPECTRO BULK 20w50, 275 gal tote	$6.50	22.75
2	NGK STANDARD SPARK PLUG (DCPR7E)	$6.95	13.90
1	FA409HH EBC BRAKE PADS	$48.44	48.44
1	GASKET, CLUTCH COVER (HD ONLY)	$26.98	26.98
1	FILTER AIR WASH 14-16TOUR	$49.95	49.95
1	16R - TIRE AM ELT 180/65B16 81H	$396.95	396.95
1	16F - TIRE AM ELITE MT90B16 72H	$236.95	236.95

Repair Description

Twin Cam Touring 07-UP - Premium service
PREMIUM DETAIL

Other Charges

Shop Supplies	22.54
Tire & Waste Disposal	0.00
Local Deliv and PU	0.00
Storage Fees	0.00
Labor Discount	0.00
Other Total	22.54

Labor	Hrs.	Rate	Amount
Premium service	1.75	$125.00	$218.75
Replace Rear Brake Pads	0.50	$125.00	$62.50
M&B Front and Rear Tires	2.10	$125.00	$262.50
Bench detail	1.25	$125.00	$156.25
Wash bike	0.50	$125.00	$62.50

****The Repair Order documents the parts and labor that we invested in preparing this vehicle for resale, and is not an additional charge.****

Parts Total $815.09

Unit Information

2015 HARLEY DAVIDSON FLHR Road King® Base
1HD1FBM11FB693769

Labor Total	$671.00
Parts Total	$815.09
Sublet Total	$0.00
Other Total	$22.54
SUBTOTAL	$1,508.63
Tax	0.00
TOTAL	**$1,508.63**