

National Powersports-Pembroke

319 Commerce Way
 Pembroke, NH 03275
 603-410-4120

Repair Order Summary

336604

****The Repair Order documents the parts and labor that we invested in preparing this vehicle for resale, and is not an additional charge.****

Qty	Part Description	Price	Amount
1	OIL FILTER CHR TWIN CAM	\$11.61	11.61
1	ORING DRAIN PLUG	\$0.95	0.95
4	SPECTRO BULK 20w50, 275 gal tote	\$6.50	22.75
1	2014 Harley Dyna Switchback OEM HD Front	\$352.00	352.00
1	DUNLOP AMERICAN ELITE FRONT - 130/70B18	\$268.95	268.95
1	BUSHINGS RISER POLYURTHN	\$11.95	11.95
1	GRIP SM DIA W/SLV 04-16	\$15.95	15.95
1	BULB MINATURE 3157	\$2.99	2.99
1	BLEEDER SCREW	\$15.83	15.83

Repair Description
Twin Cam Dyna 06-UP - Premium service PREMIUM DETAIL

Other Charges

Shop Supplies	27.50
Tire & Waste Disposal	5.00
Local Deliv and PU	0.00
Storage Fees	0.00
Labor Discount	0.00

Other Total 32.50

Labor	Hrs.	Rate	Amount
Replace Front Fender	1.00	\$125.00	\$125.00
Premium service	1.50	\$125.00	\$187.50
Repair Inop brake light	0.20	\$125.00	\$25.00
Replace grips	0.50	\$125.00	\$62.50
Mount and balance front tire	1.00	\$125.00	\$125.00
Flush brakes	1.00	\$125.00	\$125.00
Replace riser bushings	0.50	\$125.00	\$62.50
Wash bike	0.50	\$125.00	\$62.50
Bench detail	1.25	\$125.00	\$156.25

****The Repair Order documents the parts and labor that we invested in preparing this vehicle for resale, and is not an additional charge.****

Parts Total \$702.98

Labor Total	\$819.50
Parts Total	\$702.98
Sublet Total	\$0.00
Other Total	\$32.50

Unit Information
2013 HARLEY DAVIDSON FLD Dyna® Switchback™ 1HD1GZM10DC308070

SUBTOTAL \$1,554.98
Tax 0.00

TOTAL \$1,554.98