

National Powersports

319 Commerce Way
 Pembroke, NH 03275
 603-410-4120

Repair Order Summary

45261

****The Repair Order documents the parts and labor that we invested in preparing this vehicle for resale, and is not an additional charge.****

Qty	Part Description	Price	Amount
1	DAMPENER KIT BLK	\$29.95	29.95
1	SAE EYELET CONNECTOR	\$7.95	7.95
1	HORN UNIV 76MM 110DB	\$16.95	16.95
1	DAMPENER KIT BLK	\$29.95	29.95
1	BATTERY MNT FREE.93 LITER	\$170.95	170.95
2	SPARK PLUG	\$8.95	17.90
1	BREATHER TUBE 29502-	\$22.95	22.95
1	TAILLIGHT SMK/TOP LO PRO	\$167.39	167.39
1	VOLT REGULATOR, 38AMP/3-PHASE	\$190.08	190.08
1	UPPER + LOWER BELT GUARD	\$255.17	255.17
1	ROTOR ASY	\$140.26	140.26
1	SPACER	\$3.78	3.78
1	COMPENSATING NUT 91-06	\$21.79	21.79
1	PRI CVR GSKT 94-06 ST	\$37.95	37.95
1	HVY PRIMARY CHAINCASE OIL	\$12.99	12.99

Repair Description
CHANGE HANDLEBAR BUSHINGS
Blue Tag Prep
CHANGE TAILLIGHT
install voltage regulator
INSTALL BELT GUARD
Replace stator rotor

Other Charges

Shop Supplies	25.50
Tire & Waste Disposal	0.00
Local Del & PU	0.00
Storage Fees	0.00
Labor discount	0.00

Other Total 25.50

Labor	Hrs.	Rate	Amount
CHANGE BUSHINGS	1.00	\$125.00	\$125.00
BENCH DETAIL	1.25	\$125.00	\$156.25
MECHANICAL PREP	0.87	\$125.00	\$108.75
WASH MACHINE	0.50	\$125.00	\$62.50
CHANGE TAILLIGHT	0.75	\$125.00	\$93.75
voltage regulator	2.00	\$125.00	\$250.00
INSTALL BELT GUARDS	0.18	\$125.00	\$22.50
REPLACE STATOR ROTOR	0.37	\$125.00	\$46.25

****The Repair Order documents the parts and labor that we invested in preparing this vehicle for resale, and is not an additional charge.****

Parts Total \$1,126.01

Labor Total \$761.20
Parts Total \$1,126.01
Sublet Total \$0.00
Other Total \$25.50

Unit Information

2004 HARLEY DAVIDSON FXST SOFTAIL STANDARD
 1HD1BVB194Y086674

SUBTOTAL \$1,912.71

Tax 0.00

TOTAL \$1,912.71